Inspection Report

Provided by:



Inspector: Michael Kirby Phone: 785-491-0576

Property Address:

1111 Nowhere Dr



Table Of Contents:

Section name: Section number: **Report Information** 1 **Report Summary Page** 2 Grounds 3 Exterior 4 Roofing 5 Heating - Air 6 Electrical 7 Plumbing 8 Interiors 9 Kitchen Bath(s) **Basement** Garage - Laundry Foundation - Crawl Space

	1 Report Information
<u>Client Information</u>	
Client Name	Michael Kirby
Client Phone	000-000-0000
Property Information	
Approximate Year Built	2000
Approximate Square Footage	1500
Number of Bedroom	3
Number of Bath	2
Direction House Faces	South
Inspection Information	
Inspection Date	11/8/2018
Inspection Time	11:30am to 1:00
Weather Conditions	Dry
Outside Temperature	30°F
Price for Inspection	 \$350 Payment forms accepted : Cash, Credit Card or Check. Payment may be made in person or by mail. Please make checks payable to Michael Kirby. Please mail to: 38570 Pioneer Rd Maple Hill KS, 66507

WITHIN THE SCOPE OF THE INSPECTION

The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See Standards of Practice for a detailed description of the scope of inspection.

Exterior:

Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

Interior:

Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible) (as to evidence of water damage and general condition.)

- The scope of the inspection is limited to the description and the general condition of the above systems.

OUTSIDE THE SCOPE OF THE INSPECTION

-Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection.
-The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;

- Building code or zoning ordinance violations - Thermostatic or time clock controls or Low Voltage wiring systems - Geological stability or soils conditions - Water softener or water purifier systems or solar heating systems - Structural stability or engineering analysis - Saunas, steam baths, or fixtures and equipment - Building value appraisal or cost estimates - Pools or spa bodies or sprinkler systems and underground piping - Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters - Furnace heat exchanger, freestanding appliances, security alarms or personal property - Specific components noted as being excluded on the individual system inspection form - Adequacy or efficiency of any system or component - Prediction of life expectancy of any item.

- The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

CONFIDENTIAL REPORT

-The written report to be prepared by the Inspector shall be considered the final and exclusive findings of the Inspector/Inspection Company regarding the home inspection at the Inspection Address. The inspection report to be prepared for the Client is solely and exclusively for the Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person with the exception of the seller and/or the real estate agents directly involved in this transaction. Client(s) or the inspector may distribute copies of the inspection report to the seller and real estate agents directly involved in this transaction, but neither the seller nor the real estate agent are intended beneficiaries of this Agreement or the inspection report. Client agrees to indemnify, defend, and hold the Inspector/inspection Company harmless from any third party claims arising out of the Client's or Inspectors distribution of the inspection report.

DISPUTES

• Client understands and agrees that the Inspector/Inspection Company is not an insurer, that the price paid for the subject inspection and report is based solely on the service provided. Client also agrees that any claim of failure in the accuracy of the report shall be reported to the Inspector/Inspection Company within five business days of discovery and that failure to notify the inspector within that time period shall constitute a waiver of any and all claims. The Inspector/Inspection Company shall have five business days to respond to the claim. If the Inspector/Inspection Company fails to satisfy the claim, liability shall be limited to a refund of the price paid for the Inspector and Report.

Definition of conditions:

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.

S = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

2 Report Summary Page

Section	Condition#	Comment
Grounds	1	The grading around the house appears to be less than the recommended 6 inches slope within the first 10 feet of run. There are some places around the front of the house and the west side of the house where the grade appears to drain towards the foundation. Improper grading may allow for water intrusion
Grounds	3	The earth appears to have washed out from under the font sidewalk and porch, undermining may lead to cracks and sinking in the sidewalk and porch. Repair is suggested.
Exterior	7	The window in the kitchen above the sink does not appear to open. The window in the master bathroom does not appear to open.
Exterior	10	The chimney flue pipe appears to have some rust. Repair may not be required but further inspection by a certified chimney sweep is recommended. Note this is not a fireplace or wood stove chimney, it is the flue pipe for the HVAC and water heater exhaust.
Plumbing	27	The TPR valve drain pipe should terminate no more than 6 inches above the floor. Currently the drain pipe attached to the TPR valve is a flexible piece of hose that does not drain to the floor. This is considered a safety issue and should be repaired as soon as possible.
Interiors	30	The tile near the front entrance are cracked and numerous places
Interiors	32	The window in the kitchen above the sink and the window in the master bathroom will not open.
Interiors	33	Laundry room interior door does not appear to latch. Front entrance closet door does not appear to latch. The door catch for the Southwest bedroom is bowed out not allowing door to close properly.
Interiors	37	Only one smoke detector was noted at the time of the inspection. Smoke detectors are recommended by the CPSC for each room in the house.
Kitchen	42	Window above the sink does not function
Kitchen	44	There are smoke stains on the electrical outlet in the dining room. This is a safety concern, further inspection by an electrician is recommended.
Kitchen	47	The kitchen countertop appears to be pulling away from the wall
Kitchen	51	The front left burner does not appear to function

This is only a summary of the inspection report and is not a complete list of discrepancies.

I	+	łł
Bath(s)	54	Peeling paint on the wall in the master bathroom
Bath(s)	58	Window in the master bathroom does not appear to open
Bath(s)	65	Low pressure noted in all bathroom sinks and showers. The caulking between the base and shower wall in the shower of the basement bathroom appears to be cracking which may allow water to drain into the spaces behind the shower wall. Further inspection by a plumber is recommended.
Bath(s)	66	Toilet in the master bathroom does not appear to flush properly. Moisture around the base of the toilet in the main bathroom, this may be a sign of a leak. Further inspection by a plumber is recommended.
Basement	73	The basement door is weather protected by a storm shelter entrance. The roofing and interior framing is rotting in places. Further inspection and repair is recommended.
Garage - Laundry	86	There are storage shelfs in the garage that appear to have been installed professionally. These shelfs may not be secure. Further inspection by a construction professional would be required to determine the integrity of the construction.

	3 Grounds
<u>Grading</u>	
Grading Slope	Contact a landscaper or general contractor for further inspection and repair.
1) Grading Conditions	R The grading around the house appears to be less than the recommended 6 inches slope within the first 10 feet of run. There are some places around the front of the house and the west side of the house where the grade appears to drain towards the foundation. Improper grading may allow for water intrusion
<u>Driveways - Sidewalks -</u>	Walkways
Driveway Material	Concrete

2) Driveway Conditions

concret

AS

Appears to be in serviceable condition. There are some minor cracks and sinking that is normal for the age and use of the concrete.



Sidewalk Material

Concrete

3) Sidewalk Conditions



The earth appears to have washed out from under the font sidewalk and porch, undermining may lead to cracks and sinking in the sidewalk and porch. Repair is suggested.



4 Exterior

<u> Front - Back Entrance</u>	
Front Entrance Type	Covered Porch
4) Front Entrance Conditions	AS
Back Entrance Type	Deck
5) Back Entrance Conditions	AS There is a bush overhanging the stairs to the back porch



Exterior Walls

Structure Type

Exterior Wall Covering

6) Exterior Wall Conditions



Wood frame

Wood Siding and Brick

Attic Ventilation

Exterior Windows - Doors		
Window Type	Casement	
Window Material	Vinyl and Aluminum	
7) Window Conditions	R The window in the kitchen above the sink does not appear to open. The window in the master bathroom does not appear to open.	
8) Exterior Door Conditions	AS	
Exterior Water Faucet(s)		
Faucet Location	West and south sides of the house.	
9) Faucet Conditions	AS	
<u>Chimney</u>		
10) Chimney Conditions	R The chimney flue pipe appears to have some rust. Repair may not be required but further inspection by a certified chimney sweep is recommended. Note this is not a fireplace or wood stove chimney, it is the flue pipe for the UVAC and water bector subcast.	
	the flue pipe for the HVAC and water heater exhaust.	
Roof Covering	5 Roofing	
Method of Inspection	The roof was inspected by walking the safe and accessible areas.	
Roof Style	Gable	
-		
Roof Covering Material	Asphalt composition shingles.	
Number of Layers	One	
11) Roof Covering Condition	AS	
12) Flashing Conditions	AS	
13) Gutter & Downspout Conditions	AS	
<u>Attic Area</u>		
Attic Access	Garage	
Method of Inspection	The attic was inspected by partially entering due to blocked access and / or personal item storage.	
Roof Frame Type	The roof framing is constructed with truss framing.	
14) Attic Conditions	AS	
Attic Ventilation Type	Ridge Vents	
Attic Ventilation	Appeared serviceable	

Conditions		
Attic Insulation Type	Loose fill	
15) Attic Insulation Conditions	AS	
	6 Heating - Air	
<u>Heating</u>		
Location of Unit	Basement	
Heating Type	Forced Air	
Energy Source	Natural Gas	
16) Unit Conditions	AS	
Distribution Type	The visible areas of the heat distribution system is ductwork with registers.	
17) Distribution Conditions	AS	
18) Ventilation Conditions	AS	
19) Thermostat Condition	AS Thermostat is located in the hall on the main floor near the main bathroom.	
<u>Air Condition - Cooling</u>		
Type of Cooling System	Split system	
AC Unit Power	240V	
20) AC Unit Conditions	AS	
	7 Electrical	
<u>Service Drop - Weatherhe</u>	ad	
Electrical Service Type	The electrical service is underground.	
Electrical Service Material	Copper	
21) Electrical Service Conditions	AS	
<u>Main Electrical Panel</u>		
Main Disconnect Location	At Main Panel	
Electric Panel Location	The main electric panel is located at the basement. On the north wall behind a hinged wood panel door.	
Panel Amperage Rating	The electrical capacity of main breaker was listed / labeled as 200 amps.	
Circuit Protection Type	Breakers	

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

22) Wiring Methods	AS Plastic insulated (romex) type wire is present.	
23) Electrical Panel Conditions	AS	
	8 Plumbing	
Water Main Line		
Main Shutoff Location	Appears to be in the basement near the south wall. The pipe is strapped to a floor joist.	
Main Line Material	The visible material of the main line / pipe appears to be copper.	
24) Main Line & Valve Conditions	AS	
Water Supply Lines		
Supply Line Material	The visible material used for the supply lines is copper.	
25) Supply Line Conditions	AS	
Drain - Waste Lines		
Drain Line Material	The visible portions of the waste lines are plastic.	
26) Drain Line Conditions	AS	
Water Heater(s)		
Water Heater Type	Natural Gas	
Water Heater Location	Basement	
Water Heater Capacity	40 Gallon	
27) Water Heater Conditions	S The TPR valve drain pipe should terminate no more than 6 inches above the floor. Currently the drain pipe attached to the TPR valve is a flexible piece of hose that does not drain to the floor. This is considered a safety issue and should be repaired as soon as possible.	



Tpr valve will not drain properly


9 Interiors

Walls - Ceilings - Floors

28) Wall Conditions



There are a few small cracks in some places in the walls near coroners



29) Ceiling Conditions



There is a stain on the ceiling in the dining room. This could be caused by a leak from the attic, however no evidence of a leak was observed during the attic inspection.



30) Floor Conditions



The tile near the front entrance are cracked and numerous places



31) Heat Source Conditions

Windows - Doors

32) Interior Window Conditions

33) Interior Door Conditions

Electrical Conditions

34) Electrical Conditions

35) Lighting Conditions





The window in the kitchen above the sink and the window in the master bathroom will not open.



AS

AS

Laundry room interior door does not appear to latch. Front entrance closet door does not appear to latch. The door catch for the Southwest bedroom is bowed out not allowing door to close properly.

36) Ceiling Fan Conditions	AS
37) Smoke Detector Conditions	S Only one smoke detector was noted at the time of the inspection. Smoke detectors are recommended by the CPSC for each room in the house.
	10 Kitchen
<u> Walls - Ceilings - Floors</u>	
38) Wall Conditions	AS
39) Ceiling Conditions	AS
40) Floor Conditions	AS
41) Heat Source Conditions	AS
<u>Windows - Doors</u>	
42) Kitchen Window Conditions	R Window above the sink does not function
43) Kitchen Door Conditions	AS
Electrical Conditions	
44) Electrical Conditions	S There are smoke stains on the electrical outlet in the dining room. This is a safety concern, further inspection by an electrician is recommended.



45) Lighting Conditions



46) Ceiling Fan Conditions



Kitchen Sink - Counter tops - Cabinets

47) Counter Conditions The kitchen countertop appears to be pulling away from the wall R



49) Sink Plumbing	
Conditions	

50) Garbage I	Disposal
Condition	

Appliances

Stove - Range Type	The oven and range are electric.
--------------------	----------------------------------

AS

AS

51) Stove - Range The front left burner does not appear to function R Condition 52) Hood Fan AS Conditions 53) Dishwasher AS Conditions 11 Bath(s) Walls - Ceilings - Floors

54) Wall Conditions

ſ	R]
ſ	AS]

Peeling paint on the wall in the master bathroom

55) Ceiling Conditions

AS	

56) Floor Conditions

57) Heat Source Conditions	AS
Windows - Doors	
58) Bathroom Window Conditions	R Window in the master bathroom does not appear to open
59) Bathroom Door Conditions	AS
Electrical Conditions	
60) Electrical Conditions	AS
61) Lighting Conditions	AS
62) Vent Fan Conditions	AS
<u>Bathroom Sink</u>	
63) Counter - Cabinet Conditions	AS
64) Sink Conditions	AS

Shower - Tub - Toilet

65) Shower - Tub Conditions Low pressure noted in all bathroom sinks and showers. The caulking between the base and shower wall in the shower of the basement bathroom appears to be cracking which may allow water to drain into the spaces behind the shower wall. Further inspection by a plumber is recommended.





R

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected


Moisture around the base of the toilet in the main bathroom, this may be a sign of a leak. Further inspection by a plumber is recommended.

	a sign of a leak. Further inspection by a plumber is recommended.
	12 Basement
<u>Walls - Ceilings - Floors</u>	
67) Basement Stair Conditions	AS
68) Wall Conditions	AS
69) Ceiling Conditions	AS Some stains on the drop ceiling
70) Floor Conditions	AS
71) Heat Source Conditions	AS
<u>Windows - Doors</u>	
72) Basement Window Conditions	AS
73) Basement Door Conditions	R The basement door is weather protected by a storm shelter entrance. The roofing and interior framing is rotting in places. Further inspection and repair is recommended.



storm shelter entrance exterior





Electrical Conditions

74) Electrical Conditions	AS
75) Lighting Conditions	AS
76) Sump Pump Conditions	AS

13 Garage - Laundry

Walls - Ceilings - Floors

Garage Type	The ga
77) Siding Conditions (if detached)	AS
78) Roof Conditions (if detached)	AS
79) Wall Conditions	AS
80) Ceiling Conditions	AS
81) Floor Conditions	AS
82) Door Conditions	AS
83) Vehicle Door Conditions	AS
84) Electrical Conditions	AS

The garage is attached to the house.

85) Lighting Conditions



86) Garage Condition

S

There are storage shelfs in the garage that appear to have been installed professionally. These shelfs may not be secure. Further inspection by a construction professional would be required to determine the integrity of the construction.



Laundry Room

Location

The laundry facilities are located near the kitchen area just inside from the garage.

87) Laundry Room Conditions



There is a 250 volt outlets and two 120-volt outlets. Hot and cold water hook up for the washer. There does not appear to be a gas line installed for gas dryers. Dryer ventilation Goes through the floor of the laundry room

	Toolin	
14 Foundation - Crawl Space		
Foundation		
Foundation Type	Basement	
Foundation Material	Concrete	
88) Foundation Conditions	AS	
Flooring Structure		
Flooring Support Type	The wood framing floor system appeares to be constructed of 2 X 10 floor joists.	
89) Flooring Support Conditions	AS	